

Safety Issue Type: Recalls

March 07 2017 NHTSA Campaign Number: 17V145000

Anti-Lock Brakes may not Function Properly

If the ABS does not function properly in a braking event, there is an increased risk of a crash.

NHTSA Campaign Number 17V145000

Manufacturer Zero Motorcycles Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 61

Summary

Zero Motorcycles Inc. (Zero) is recalling certain 2017 S, DS, and FXS motorcycles. The Anti-Lock Braking System (ABS) Hydraulic Control Unit (HCU) may have the wrong vehicle model information, possibly causing the ABS to function improperly.

Remedy

Zero will notify owners and dealers will reconfigure the HCU, or replace it as needed, free of charge. The recall is expected to begin March 20, 2017. Owners may contact Zero customer service at 1-888-841-8085. Zero's number for the recall is SV-ZMC-017-363.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Associated Products (3)

Vehicle

MAKE	MODEL	YEAR
ZERO	S	2017
ZERO	FXS	2017
ZERO	DS	2017

Associated Documents (1)

Defects Notice 573 Report

RCLRPT-17V145-5470.PDF 217.373KB

<https://static.nhtsa.gov/odi/rcl/2017/RCLRPT-17V145-5470.PDF>